

Fig. 1A




Fig. 1B




Fig. 1C




Fig. 2A




Fig. 2B




Fig. 2C




Fig. 2D




Fig. 2E




Fig. 3




Fig. 4




Fig. 5




Fig. 6




Fig. 7

Application of Adhesivelybonded Heat Shrink Tube to
Bragg Sensor




Fig. 8

Bragg Sensor Measurement of Coating Wear




Fig. 9




Fig. 10




Fig. 11




Fig. 12




Fig. 13




Fig. 14




Fig. 15